

## **FleetBroadband 150, 250 & 500 and EXPLORER 727 & 325 Upgrade - ver. 1.14**

Please be informed that a new software version 1.14 for the Thrane & Thrane BGANX platform SAILOR 500, SAILOR 250, Sailor 150, EXPLORER 727 & Explorer 325 has been released and is available to download from ASTs Extranet: <http://www.astextranet.com/ASTFileRetrieval.aspx?key=d20c46f6-1e0e-4daa-ac99-ba280dbb1edf>

**Priority:**

**MEDIUM:** It is recommended to apply this change.

**What this firmware does:**

- New features and improvements related to SAILOR 500, SAILOR 250, SAILOR 150, EXPLORER 727 and EXPLORER 325:
  - EXPLORER 727 - Support of Class 1 operation for EXPLORER 727 when stationary. While moving Class 10 operation is still being supported. Note: To change terminal operation mode using the Thrane & Thrane IP handset requires a Thrane & Thrane IP handset that has been upgraded to SW rel. 1.12.
  - SAILOR 500 / 250 / 150 – Voice Distress (None-SOLAS) on SAILOR 500 / 250 / 150 established via Alarm Panel. This function is only available when installing a SAILOR 3771 Alarm Panel FleetBroadband
  - Note: This function requires a Thrane & Thrane IP handset that has been upgraded to SW rel. 1.12
  - SAILOR 500 / 250 / EXPLORER 727 / 325 - Automatic VoIP Handset User ID and Password configuration. This is a feature which will automatically provide next free User Id and Password (0502 - 0516) when yet another IP Handset is attached the Terminal /Switch (first IP Handset is default set to 0501).

AST recommend that BGAN customers run the latest versions of firmware.

**If you have any questions or have an issue downloading the firmware, please contact AST Customer Service on:**

**Log a Ticket:** <http://customerservice.satcomms.com/>

**Email:** [customer.service@ast-uk.com](mailto:customer.service@ast-uk.com)

**Tel:** +44 (0) 1493 441485

**Skype:** AST Customer Service